

**US 9 and SR 5 Intersection Improvements Project, Harbeson, Sussex County, Delaware
Architectural Survey and Evaluation**

**John Milner Associates, Inc. (Courtney L. Clark)
Photo Log – July 2012**

Beaver Dam Cemetery/Harbeson Cemetery, SW Corner of US 9 & SR 5

- S03531_001 Cemetery, looking southwest from northeast corner of Harbeson Road and Lewes Georgetown Highway intersection.
- S03531_002 Cemetery, looking west-northwest from east side of Harbeson Road.
- S03531_003 Cemetery, looking southwest from corner of main entrance along Harbeson Road.
- S03531_004 Cemetery, looking west along main entrance off Harbeson Road.
- S03531_005 Cemetery, looking west-northwest from corner of main entrance along Harbeson Road.
- S03531_006 Gazebo in cemetery, looking southwest.
- S03531_007 Cemetery, looking east-northeast.

Beaver Dam School No. 88 / Harbeson Church Hall, 18636 Harbeson Road

- S03532_008 Church hall façade, looking west from east side of Harbeson Road.
- S03532_009 Church hall façade and south side, looking west-northwest.
- S03532_010 Church hall rear and north side, looking southeast.
- S03532_011 Church hall rear and south side, looking northeast.

Johnson / Rust Dwelling, 18672 Harbeson Road

- S03533_012 Dwelling (.001) façade and north side, looking southwest.
- S03533_013 Dwelling (.001) façade, looking west.
- S03533_014 Dwelling (.001) south side, looking northwest.
- S03533_015 Dwelling (.001) north side, looking south.
- S03533_016 Dwelling (.001) rear and north side and rear lawn structure (.002), looking southeast.
- S03533_017 Rear lawn structure (.002), looking south.
- S03533_018 Modern garage with attached shed, looking east.

Dwelling, 18678 Harbeson Road

- S03534_019 Dwelling (.001) façade, looking west.
- S03534_020 Dwelling (.001) north side, looking southwest.
- S03534_021 Detail of decorative curved gables along roof ridge of dwelling.
- S03534_022 Dwelling (.001) south side, looking north.
- S03534_023 Dwelling (.001) rear wall, looking east.
- S03534_024 Shed and outbuilding (.002), looking west.
- S03534_025 Dwelling (.001) rear, outbuilding (.002) and shed, looking northeast.

Rust Dwelling, 18675 Harbeson Road

- S03564_026 Dwelling (.001) façade and north side and outbuilding (.002), looking east.
- S03564_027 Dwelling (.001) façade and south side, looking east-northeast.
- S03564_028 Dwelling (.001) rear and north side, looking southwest.
- S03564_029 Detail of decorative bracket along roof ridge of dwelling.

- S03564_030 Dwelling (.001) south side and rear outbuildings (.002, .003, .004), looking northeast.
 S03564_031 Garage (.002) façade and north side, looking southeast.

Barker / Wagamon Dwelling, 18665 Harbeson Road

- S03565_032 Dwelling façade and north side, looking east-southeast.
 S03565_033 Dwelling façade and north side, looking southeast.
 S03565_034 Dwelling north side, looking south-southwest.
 S03565_035 Dwelling rear enclosure and addition, looking south.
 S03565_036 Dwelling south side, looking northwest.

Dwelling / Harbeson United Church Parsonage

- S03566_037 Garage (.002) and shed, looking east.
 S03566_038 Garage (.002) and shed, looking north.

Beaver Dam Methodist Protestant Church / Harbeson United Methodist Church

- S03567_039 Church (S03567) and outbuildings (modern and S03566.002), looking east-northeast.
 S03567_040 Church (.001) façade and north side, looking southeast.
 S03567_041 Church (.001) rear and south side, looking northwest.
 S03567_042 Church (.001) rear and north side, looking west-southwest.
 S03567_043 Detail of 1885 datestone on north wall of church.
 S03567_044 Detail of 1927 datestone on north, front wall of church.

Davidson Dwelling

- S03569_045 Dwelling (.001) façade and west side, looking north-northeast.
 S03569_046 Dwelling (.001) rear and west side, looking southeast.
 S03569_047 Dwelling (.001) rear and east side, looking southwest.
 S03569_048 Garage (.002) façade and west side, looking northeast.
 S03569_049 Garage (.002) and modern building, looking north.

Dwelling, NW corner of Harbeson Road (SR 5) & Lewes Georgetown Hwy (US 9/SR 404)

- S03573_050 Dwelling façade and north side, looking west-southwest.
 S03573_051 Dwelling south side, looking north.
 S03573_052 Dwelling rear, looking northeast.

Prettyman Complex / Compass Point Associates

- S03574_053 Dwelling (.001), garage (.002) and water fountain (.003), looking northwest.
 S03574_054 Dwelling (.001) façade and west side, looking northeast.
 S03574_055 Dwelling (.001) façade and east side, looking northwest.
 S03574_056 Dwelling (.001) rear, south-southeast.
 S03574_057 Outbuilding (.003), looking northeast.
 S03574_058 Outbuilding (.004) west side, looking east.
 S03574_059 Outbuilding (.004) façade and east side, looking northwest.
 S03574_060 Water fountain (.006), looking northwest.

Dwelling, 18557 Harbeson Road

- S03645_061 Dwelling façade and north side, looking east.
 S03645_062 Dwelling south side, looking northeast.
 S03645_063 Dwelling north side, looking southeast.

Dwelling, 26483 Lewes Georgetown Highway

- S08502_064 Dwelling façade and west side, looking north.
- S08502_065 Dwelling rear and west side, looking southeast.
- S08502_066 Dwelling façade and west side, looking north.

Dwelling, 26504 Lewes Georgetown Highway

- S08503_067 Dwelling façade and west side, looking southeast.
- S08503_068 Dwelling façade and east side, looking south.
- S08503_069 Dwelling rear and west side, looking north.
- S08503_070 Modern garage to rear of dwelling.
- S08503_071 Agricultural outbuildings to rear of dwelling.

Dwelling / Commercial, 26526 Lewes Georgetown Highway

- S08504_072 Dwelling façade, looking south.
- S08504_073 Dwelling façade, looking south.
- S08504_074 Dwelling rear and east side, looking northwest.
- S08504_075 Dwelling rear and west side, looking north.
- S08504_076 Modern garage to rear of dwelling.

Harbeson Historic District

- S12188_077 Harbeson HD streetscape looking northwest along Harbeson Road (at Doddtown Road T-intersection).
- S12188_078 Harbeson HD streetscape looking northwest along Harbeson Road (just north of Doddtown Road T-intersection).
- S12188_079 Harbeson HD streetscape looking southwest along Harbeson Road (south of railroad tracks).
- S12188_080 Harbeson HD streetscape looking south along Harbeson Road (south of railroad tracks).
- S12188_081 Harbeson HD streetscape looking northwest along Harbeson Road (south of railroad tracks).
- S12188_082 Detail of railroad tracks within Harbeson HD looking east-northeast from Harbeson Road.
- S12188_083 Detail of railroad tracks within Harbeson HD looking west-southwest from Harbeson Road.
- S12188_084 Harbeson HD streetscape looking north-northwest along Harbeson Road (just north of railroad tracks).
- S12188_085 Harbeson HD streetscape looking north-northeast along Harbeson Road (just north of railroad tracks).
- S12188_086 Harbeson HD streetscape looking south along Harbeson Road, between railroad tracks and Lewes Georgetown Highway.
- S12188_087 Harbeson HD streetscape looking south along Harbeson Road, between railroad tracks and Lewes Georgetown Highway.
- S12188_088 Harbeson HD streetscape looking southeast along Harbeson Road (north of railroad tracks).
- S12188_089 Harbeson HD streetscape looking north along Harbeson Road, between railroad tracks and Lewes Georgetown Highway.
- S12188_090 Harbeson HD streetscape looking northwest along Harbeson Road (north of railroad tracks).

- S12188_091 Harbeson HD streetscape looking south along Harbeson Road (just south of Harbeson Road and Lewes Georgetown Highway intersection).
- S12188_092 Harbeson HD streetscape looking south-southeast along Harbeson Road (just south of Lewes Georgetown Highway).

Culvert, Lewes Georgetown Highway

- S12260_093 Concrete ditch east of south abutment and wing walls, looking east.
- S12260_094 Bridge, north abutment and wing walls, looking southwest.
- S12260_095 Bridge, south abutment and wing walls, looking west.
- S12260_096 Remnants of masonry wall near north elements, looking west-northwest.

Culvert, Harbeson Road

- S12261_097 Culvert along west side of Harbeson Road, looking south.
- S12261_098 View of culvert along west side of Harbeson Road, looking southwest.
- S12261_099 View of culvert opening along east side of Harbeson Road, looking southwest.

Agricultural Feed Store

- S12262_100 Former feed store (001) façade and remaining south end, looking northeast.
- S12262_101 Former feed store (001) façade, looking southeast.
- S12262_102 Former weigh station (002), looking south-southeast.

Auto Garage

- S12263_103 Building façade and west side, looking north.
- S12263_104 Building façade and east side, looking north-northwest.
- S12263_105 Building rear and parts of east side, looking south-southwest.
- S12263_106 Building rear, looking south.
- S12263_107 Modern secondary building on property, looking north.

Dwelling, 26473 Lewes Georgetown Highway

- S12264_108 Dwelling (.001) façade and west side, looking northeast.
- S12264_109 Dwelling (.001) façade and east side, looking northwest.
- S12264_110 Dwelling (.001) rear, looking south.
- S12264_111 Dwelling (.001) rear and east side, looking southwest.
- S12264_112 Garage (.002) and garage (.003) façades, looking northwest.
- S12264_113 Garage (.002) and garage (.003) rears, looking south.

Dwelling, 26474 Lewes Georgetown Highway

- S12265_114 Dwelling façade and west side, looking southeast.
- S12265_115 Dwelling rear and west side, looking east-northeast.
- S12265_116 Dwelling rear, looking northwest.

Post Office / Harbeson Barber Shop

- S12266_117 Building façade and west side, looking south.
- S12266_118 Building rear and east side, looking north.
- S12266_119 Building façade and west side, looking south.
- S12266_120 Building rear and west side, looking northeast.

Dwelling, 18570 Harbeson Road

- S12267_121 Dwelling (.001) façade, looking west.
- S12267_122 Dwelling (.001) rear, looking east.

S12267_123 Dwelling (.001) and garage (.002) south side, looking north.